



MAG 2000 Impact Indicator Setup Guide

- Acts as a visual deterrent to improper handling
- Reduces mishandling through awareness
- Provides indisputable evidence of mishandling
- Promotes chain of accountability for all product handling
- Confirms effectiveness of packaging
- Helps identify trouble spots in supply chain, from production to transportation and storage

The MAG 2000 is a cost-effective, resettable, and reusable impact monitoring device for fragile shipments over 226kg (500lbs).

To set the MAG 2000 units for use, please follow this procedure:

1. Affix the unit to the desired location using adhesive or the available mounting holes.
2. Unlock the cover using the black MAG 2000 Key that accompanied your shipment. Place the Key over the MAG 2000 cover and insert the 4 prongs into the 4 slots in the MAG 2000 cover.

3. Press down firmly and turn the Key to the left until the cover loosens.

4. Remove the Key, grasp the cover and turn it to the left as far as possible.

5. Lift the cover off and put the red indicator magnet back in the center position of the MAG 2000 (red side up).

6. Place the cover back on the unit. Press down and turn it to the right until the cover clicks into place.



Inactivated



Activated



MAG 2000 Key