



# MAG 2000 Impact Indicator Setup Guide

- Acts as a visual deterrent to improper handling
- Reduces mishandling through awareness
- Provides indisputable evidence of mishandling
- Promotes chain of accountability for all product handling
- Confirms effectiveness of packaging
- Helps identify trouble spots in supply chain, from production to transportation and storage

The MAG 2000 is a cost-effective, resettable, and reusable impact monitoring device for fragile shipments over 226kg.

## The MAG2000 needs to be armed when placed on the shipment.

To arm the MAG 2000 unit for monitoring, please follow this procedure:

1. Affix the unit to the desired location using adhesive or the available mounting holes.
2. Unlock the cover using the black MAG 2000 Key. Place the Key over the MAG 2000 cover and insert the 4 prongs into the 4 slots in the MAG 2000 cover.

3. Press down firmly and turn the Key to the left until the cover loosens.
4. Remove the Key, grasp the cover and turn it to the left as far as possible.
5. Lift the cover off and move the red indicator magnet into the center position of the MAG 2000 (red side up).
6. Place the cover back on the unit. Press down and turn it to the right until the cover clicks into place.

The MAG2000 is now ready to monitor for any impacts in transit.



ARMED ready for shipment



IMPACT has occurred in transit



MAG 2000 Key