

SHOCKWATCH®
DAMAGE PREVENTION. WE'RE ON IT.

WarmMark™
10C LongRun

www.warmmark.com



Line

1

2

3

4

5

Hours at 12°C (54°F)



Hours at 22°C (72°F)



Hours at 32°C (90°F)



SHIPPING AND HANDLING MONITORS | EQUIPMENT MONITORS







Line

1 2 3 4 5


Hours at 33°C



Hours at 40°C / 104°F



Hours at 50°C / 122°F



SHIPPING AND HANDLING MONITORS | EQUIPMENT MONITORS

